


Rec'd PCT/PTO 17 JUN 2005
10 / 540083

Figure 1



BEST AVAILABLE COPY

Rec'd PCT/PTO 17 JUN 2005
10 / 540083




Figure 2

Rec'd PCT/PTO 17 JUN 2005
10/540082




Figure 3

Rec'd PCT/PTO 17 JUN 2005

10/540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 4 of 23
Express Mail # ED381139323 US




Figure 4

Rec'd PCT/PTO 17 JUN 2005
10/540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 5 of 23
Express Mail # ED381139323 US





Figure 5

Rec'd PCT/PTO 17 JUN 2005
10 / 540085

Figure 6



Rec'd PCT/PTO 17 JUN 2005
10/540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 7 of 23
Express Mail # ED381139323 US




Figure 7

Rec'd PCT/PTO 17 JUN 2005
101540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 8 of 23
Express Mail # ED381139323 US




Figure 8

Rec'd PCT/PTO 17 JUN 2005
101540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 9 of 23
Express Mail # ED381139323 US




Figure 9

Rec'd PCT/PTO 17 JUN 2005
10 / 540083





Figure 10

Rec'd PCT/PTO 17 JUN 2005
10 / 540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 11 of 23
Express Mail # ED381139323 US

Figure 11



Rec'd PCT/PTO 17 JUN 2005
10 / 540083




Figure 12

Rec'd PCT/PTO 17 JUN 2005
101540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 13 of 23
Express Mail # ED381139323 US




Figure 13

Rec'd PCT/PTO 17 JUN 2005
109540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 14 of 23
Express Mail # ED381139323 US




Figure 14A

Rec'd PCT/PTO 17 JUN 2005
10/540085

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 15 of 23
Express Mail # ED381139323 US




Figure 14B

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 16 of 23
Express Mail # ED381139323 US

Rec'd PCT/PTO 17 JUN 2005
101540083




Figure 15

Rec'd PCT/PTO 17 JUN 2005

10 / 540083




Figure 16

Rec'd PCT/PTO 17 JUN 2005
10/540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 18 of 23
Express Mail # ED381139323 US




Figure 17

Rec'd PCT/PTO 17 JUN 2005

10 / 540083




Figure 18

Rec'd PCT/PTO 17 JUN 2005
10/540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 20 of 23
Express Mail # ED381139323 US




Figure 19

Rec'd PCT/PTO 17 JUN 2005
101540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 21 of 23
Express Mail # ED381139323 US




Figure 20A

Rec'd PCT/PTO 17 JUN 2005

10/540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 22 of 23
Express Mail # ED381139323 US





Figure 20B

Rec'd PCT/PTO 17 JUN 2005

10/540083

Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 23 of 23
Express Mail # ED381139323 US

Figure 21



**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING.**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.